



A walkability audit was carried out outside the school by members of the GS committee on Nov 20th, 2024.

Findings:



If parents need to turn right out of the school they need to turn left and turn at the round about.



A shelter near the bus stop would encourage more students to use public transport.



Pencil bollards are great because they highlight the presence of the school and stop cars parking on the footpath.



Litter along the route – Raise awareness in the community about littering.



Great to have a pedestrian crossing near the school entrance.




- The footpath down to the bus stop was a little narrow and exposed to traffic.



A walkability audit was carried out outside the school by members of the GS committee on Nov 20th, 2024.



- This is a periodic speed sign. It tells traffic the speed it is travelling. If it goes over 50kmh it flashes red, if it goes under 50kmh it flashes green.



- Carrying out a speed survey outside the school..

Speed results. Most drivers were below the 50kmh speed limit.